
Subject: Re: small issues on "register" and "tLineInfrastructureManagerCode"

Posted by on Fri, 07 Dec 2012 14:37:07 GMT

[View Forum Message](#) <> [Reply to Message](#)

Dear Susanne,

> Yes, you are right. I tried to find out, when the renaming from "DS100"
> to "RL100" was done, but I couldn't find it. That's the reason for the
> blank "begin" and "end" attributes. It was my intention to show this use
> case with disjunctive validities.

As far as I know: There never was a renaming of DS100 to RL100. Only last week I got a document from DB Kommunikationstechnik (!) where it is still named "DS100". I think these are two different naming philosophies at Deutsche Bahn.

So please do not try to create examples which assume there was a naming brake of DS100 and RL100. This could be misunderstood in a way that both values are allowed. I sent you an example with a naming brake from DR to DB and ThE, so possibly you could use that.

> I'm sorry for that.

No need to be sorry. We have to be thankful for your support. Thank you!

With best regards,
Dirk.
